

CDM - RESIDUAL RISKS  
 Any residual risks which could not be fully mitigated or removed through design have been indicated within the drawing. Please refer to the Design Risk Assessments for further possible control measures which may help to mitigate these and other identified risks further during the construction / maintenance process.

Rev	Date	Reference	Drawn / Chk'd
P01	2015/11/09	P01 FIRST ISSUE	EG AW
P02	2016/03/15	P02 Amendment to drawing title	EG AW



Client  
 Oak Tree Low Carbon Farm

Project  
 Proposed Community Cafe and Training Centre, Oak Tree Farm, Rushmere, Suffolk

Title  
 Site Layout As Proposed

Drawing Ref. 3270-A-0101 Revision P02

Scale - unless otherwise stated 1:500 @ A2 Status S0 Issued For Preliminary